L Number	Hits	Search Text	DB	Time stamp
-	86	73/862.391.ccls.	USPAT	2001/11/05 13:07
-	1	73/862$3.ccls. and (measure and (stress tension strain) and (hook hanger) and hydraulic).clm.	USPAT	2001/04/19 13:00
-	3	73/862$3.ccls. and (measure and (stress tension strain) and (hook hanger handle) and hydraulic and gage)	USPAT	2001/04/19 13:02
-	6	73/862$3.ccls. and (measure and (stress tension strain) and cable and hydraulic and gage)	USPAT	2001/04/21 19:28
-	0	73/$6.ccls. and (measure and (stress tension strain) and cable and hydraulic and gage and hook and V near2 shape).clm.	USPAT	2001/04/19 13:06
-	0	73/$6.ccls. and (measure and (stress tension strain) and cable and hydraulic and gage and hook and V near2 shape)	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:06
-	0	73/$6.ccls. and (measure and (stress tension strain) and cable and hydraulic and gage).clm.	USPAT	2001/04/19 13:07
-	43	73/$6.ccls. and (measure and (stress tension strain) and cable and hydraulic and gage)	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:08
-	1	73/$6.ccls. and (measure and (stress tension strain) and cable and hydraulic and (gage gauge)).clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:09
-	137	73/$6.ccls. and (measure and (stress tension strain) and (cable line wire) and hydraulic and gage)	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:10
-	505	73/$6.ccls. and (measure and (stress tension strain) and (cable line wire) and hydraulic and (gage gauge))	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:10
-	4	73/$6.ccls. and (measure and (stress tension strain) and (cable line wire) and hydraulic and (gage gauge)).clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:14
-	0	73/144.ccls.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:12
-	5	3839908.pn.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:12
-	11	(measure and (stress tension strain weigh) and (cable line wire) and hydraulic and (gage gauge)).clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:18
-	0	(measure and (stress tension strain weigh) and (cable line wire) and (v near shape) and (gage gauge)).clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:18
-	0	(measure and (stress tension strain weigh) and (cable line wire) and (v near4 shape) and (gage gauge)).clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:20
-	1	(measure and (stress tension strain weigh) and (cable line wire) and (v near4 shape)).clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:19
-	80484	(stress tension strain weigh) and (cable line wire).clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:22

-	10275	((stress tension strain weigh) and (cable line wire).clm.) and measure	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:20
-	1025	((stress tension strain weigh) and (cable line wire).clm.) and measure.clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:20
-	122	(((stress tension strain weigh) and (cable line wire).clm.) and measure.clm.) and (gage gauge).clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:21
-	11	((((stress tension strain weigh) and (cable line wire).clm.) and measure.clm.) and (gage gauge).clm.) and jack	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:21
-	39113	(stress tension strain weigh) and (cable wire).clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:22
-	18	((stress tension strain weigh) and (cable wire).clm.) and measure and jack and (gage gauge).clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:26
-	159546	wire near stain naear gauge	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:27
-	2	wire near stain near gauge	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:27
-	5	(wire cord cable) near (stain force stress) near gauge	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:38
-	146	(wire cord cable) near4 (stain force stress) near4 gauge	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:38
-	109420	deflect(wire cord cable) near4 (stain force stress) near4 gauge	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:59
-	21	((wire cord cable) near4 (stain force stress) near4 gauge) and (deflect deflection)	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:57
-	9	((wire cord cable) near4 (stain force stress) near4 gauge) and (deflect deflection) and pull	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 13:57
-	3	deflect and(wire cord cable) near4 (stain force stress) near4 (gauge gage)and pull	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 14:02
-	856	deflect and(wire cable) and (stain force stress) and (measure$4)and pull	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 14:43
-	3	deflect and(wire cable) near4 (stain force stress) near4 (measure$4)and pull	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 14:03
-	16	73/862.39$.ccls. and pull and cable	USPAT	2001/04/19 14:15

-	82	73/862.451.ccls.	USPAT	2001/04/19 14:27
-	4	73/862.42.ccls. and pull and cable	USPAT	2001/04/19 14:24
-	205	deflect and(wire cable) and (stain force stress) and (measure$4)and pull and hydraulic	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 14:44
-	38	deflect and(wire cable) and (stain force stress) and (measure$4)and pull and hydraulic .clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 14:45
-	0	(deflect and(wire cable) and (stain force stress) and (measure$4)and pull and hydraulic) .clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/19 14:46
-	1	(deflect and(wire cable) and (stain force stress) and hydraulic) .clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/23 08:15
-	6	73/862.391.ccls. and hydraulic	USPAT	2001/04/21 19:25
-	1	73/862.391.ccls. and (hydraulic).clm.	USPAT	2001/04/21 19:25
-	0	73/862$3.ccls. and (measure and (stress tension strain) and cable and hydraulic and gage).clm.	USPAT	2001/04/23 08:46
-	2	73/862$3.ccls. and (measure and (stress tension strain) and hydraulic and gage).clm.	USPAT	2001/04/21 19:29
-	1	73/$6.ccls. and (measure and deflection and hydraulic and gage).clm.	USPAT	2001/04/23 11:52
-	538	(measure and deflection cable and hydraulic and gage).clm.	USPAT	2001/04/21 19:38
-	4	(measu$4 and deflect$4 and cable and hydraulic and (gauge gage)).clm.	USPAT	2001/04/21 19:32
-	12	(measu$4 and cable near4 deflect$4 and hydraulic and (gauge gage))	USPAT	2001/04/21 19:36
-	1	(tensiometer and cable near4 deflect$4 and hydraulic and (gauge gage)).clm.	USPAT	2001/04/23 11:51
-	535	(measure and deflection cable and hydraulic near4 jack and gage).clm.	USPAT	2001/04/21 19:39
-	535	(measure and deflection cable and hydraulic near jack and gage).clm.	USPAT	2001/04/21 19:39
-	42	(tensio$4 and measure and deflection cable and hydraulic near jack and (gage gauge)).clm.	USPAT	2001/04/21 19:50
-	3	(tensio$4 and pull near4 test$4 and deflection cable and hydraulic near jack and (gage gauge)).clm.	USPAT	2001/04/21 19:51
-	34346	cable near4 (tension pull tes$4)	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/23 08:21
-	3892	cable near4 (tension pull tes$4).clm.	USPAT; EPO; JPO; DERWENT; IBM TDB	2001/04/23 08:23
-	1152	tensiometer	USPAT	2001/04/23 08:46
-	12	(tensiometer and cable).clm.	USPAT	2001/04/23 08:46
-	3	("4907458" "3839908" "4989450").pn.	USPAT	2001/04/23 11:52
-	5	proceq	USPAT	2001/11/02 15:55
-	2	wire near tension near meter	USPAT	2001/11/02 15:56
-	373	wire near tension and concrete	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/02 16:30
-	68	wire near tension and concrete and hydraulic	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/02 16:30
-	68	(wire near tension) and concrete and hydraulic	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/02 16:50

-	25	(wire near2 tension) and concrete and hydraulic and gauge	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/02 16:51
-	108	73/862.42.ccls.	USPAT	2001/11/05 13:09
-	92	73/862.391.ccls.	USPAT	2001/11/05 13:08
-	82	73/862.381.ccls.	USPAT	2001/11/05 14:33
-	0	658118.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/05 13:30
-	0	541850.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/05 13:30
-	8	("2872808" | "3679808" | "3994162").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/05 13:40
-	1	5390550.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/05 13:40
-	1	220668.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/05 14:18
-	0	73/144.ccls.	USPAT	2001/11/05 14:36
-	64	73/158.ccls.	USPAT	2001/11/05 14:36
-	178	73/144	USPAT	2001/11/05 16:13
-	3	4374473.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/05 14:39
-	1	4989450.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/05 14:43
-	0	D297818.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/05 14:48
-	29	("D087988" | "D271669" | "D275087" | "1780141" | "2013810" | "3176510" | "3410246" | "3618379" | "4163126" | "4171640" | "4534228").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/05 14:48
-	1	4135393.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/05 14:56

-	17	("2245039" | "2591724" | "2723561" | "3495454" | "3512406").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/05 15:04
-	2	3879999.URPN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2001/11/05 15:04
-	13	(tensiometer and (wire cable)).clm.	USPAT	2001/11/05 16:15